

### Chapter 10 Case Studies of an Independent Consultant Typical Down to the Coast Growth Fault Seimsic Section




Depositional thickening as a result of contemporaneous growth faulting (From Bruce 1973)


### **Electric Log of Lower Part of S K East B-20**



#### **Location of the Salt Creek Field**




#### Three-D Structure of the Salt Creek Field.



Salt Creek 3-D Dual Buildup.

# Location of the Headington 320 Tract Purchased from Exxon.



## Drilling location Hedington East # 1 200 ft Offset to Mrs. S K. East B-20




Fig. 10-25Production build-up for the East Seven Sisters field, Duval County, Texas

